

General Environmental Incident Summary

Incident: 3285 **Date/Time Notice:** 4/12/2014 1030 **DEM Incident No:**

Responsible Party: espen dalgliesh

Date Incident: 4/11/2014 **Time Incident:** 2244 **Duration:**

County: Cass **Twp:** 141 **Rng:** 53 **Sec:** 1 **Qtr:** SE

Lat: 47.84720 **Long:** -99.77444 **Method:** Interpolation from map

Location Description: On the north side of county road 4 about 1225 feet west of 30 street

Submitted By: Mike Mead

Affiliation:

Address: 4100 32 avenue sw

City: Fargo

State: ND

Zip: 58104

Received By:

Contact Person:

2360 143rd ave se
Ayr, ND 58007

Distance Nearest Occupied Building: 0.5 Miles

Release Contained: Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: mineral oil 75 to 100 gallons estimated

Volume Spilled: 100.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

A car went off the road and hit our pole that had three electrical regulators on the pole. Regulators fell to the ground with the pole and mineral oil leaked out.

Risk Evaluation:

None,

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

None, oil spilled cleaned up to the best of our ability.

Action Taken or Planned:

Contained leak by bagging regulators, remove saturated soil and put down spill mats. Regulators don't have PCB, but as per our procedure, an oil sample will be pulled and sent for testing.

Wastes Disposal Location: Land fill once oil sample results are received.

Agencies Involved:

Updates

Date: 4/12/2014 **Status:** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Vehicle struck utility pole causing release of mineral oil from electrical transformer on the pole. Report indicates that the mineral oil is PCB free, but it will be tested to be sure. NDDoH Waste Management Division will conduct any followup necessary.

Date: 4/23/2014 **Status:** Reviewed - No Action Required

Author: Tintes Schiwal, Emily

Updated Volume:

Notes:

The mineral oil test results came back as negative for PCBs. The contaminated soils will be disposed of at the City of Fargo landfill.